


## KABELLÖSUNG

Neu bei METZGER:  
Ölstopp-Kabel für Anschlussleitung  
Nockenwellenversteller Mercedes-Benz: A 271 150 27 33

### Innovation: Ölstoppteitungsverbinder Ölindikator-Litze

„Verbesserte  
Version“

Der Ölverlust am Nockenwellenversteller ist bei bestimmten Mercedes-Benz Motoren ein bekanntes Problem. Durch die Kapillarwirkung kann das Öl im Kabelbaum bis zum Steuergerät gelangen. Dies kann zum Ausfall der Elektronik führen. Durch das Metzger „Ölstoppkabel“ wird ein Eindringen von Öl in den Kabelbaum wirksam verhindert.



#### Ölstoppleitungsverbinder

- Korrosionsfrei
- Verbindungstechnologie gemäß
  - Norm DIN EN 60352-2
  - VW Norm Group Standard VW 60330

**METZGER Artikelnummer: 2324048**



OE-Nummern dienen nur zu Vergleichszwecken



Werner Metzger GmbH    Telefon +49 711 / 160 86 - 0  
Rita-Maiburg-Str. 33    Telefax +49 711 / 160 86 - 86  
D-70794 Filderstadt    E-mail info@werner-metzger.de

[www.werner-metzger.de](http://www.werner-metzger.de)

## CABLE SOLUTION

New at METZGER:


Oil stop cable for connecting lead camshaft adjuster  
Mercedes Benz: A 271 150 27 33

### Innovation:

Oil stop line connector  
Oil indicator stranded wire

„Improved  
Version“

The loss of oil at the camshaft adjuster is a known problem with certain Mercedes-Benz engines. Due to the capillary effect, the oil in the wiring harness can reach the control unit. This can lead to failure of the electronics. The Metzger's „oil stop cable“ effectively prevents oil from penetrating the wiring harness.



#### Oil stop line connector

- Corrosion-free
- Connection technology according to
  - Standard DIN EN 60352-2
  - VW Norm Group Standard VW 60330

Part number 2324048



OE numbers are for comparison purposes only



Werner Metzger GmbH  
Rita-Maiburg-Str. 33  
D-70794 Filderstadt

phone +49 711 / 160 86 - 21  
fax +49 711 / 160 86 - 86  
E-mail [export@werner-metzger.com](mailto:export@werner-metzger.com)

[www.werner-metzger.com](http://www.werner-metzger.com)